Wapiti Nordic Equipment

Grooming



1) **Compaction Drag.** With Cutters and fold down comb.

Condition: Good but rusty

Recommend: KEEP



2) Mesh Screen Harrow. 5' Long by 4' 3" wide

Condition: Fair - Edge wires bent, missing or partially pulled

away.

Recommend: SELL/DISCARD



3) YTS Screen Roller.

Condition - Good, but suggest Inspection of Bearings.

Recommend: KEEP



4) Wooden Compaction Drag.

Condition - Rotted. Salvage any useful parts. Recommend DISCARD



5) 4X4 Timbers.

Condition - Fair (Repurpose timbers eg. Biathlon outhouse steps.)

Recommend: REPURPOSE



6) **Tracksetter** (with pre-cutters)

Condition - Fair (Surplus to Requirement)
Recommend: ??? UNDECIDED.MORE INPUT REQUIRED.



7) Steel Toboggan

Condition - Good Recommend: KEEP



8) Wooden Levelling Drag?? (Unknown tool)

Condition - Very Poor. Recommend: <u>DISCARD</u>



9) **HD Levelling Drag** (2.5" X 2.5" square tubing; 5' ft wide)

With fold down Comb.

Recommend: KEEP (FOR REASSESSMENT AT LATER DATE)



10) Surfacing Drag (Yellow) 5' wide X 5' 3" Long

has 3 sections of vertical steel slats

Recommend: KEEP



11) Very HD Levelling/Compaction Drag

This drag was build by Dominic. It's not very useable due To its weight. It tends to submarine into the snow rather than staying on the surface when pulled. It has a fold comb and a row of cutters to cut and move snow that are depth adjustable via the screw wheel at the rear.

Recommend: <u>SELL</u> (SKIDOO CLUB??)



13) Ripping Drag (with replaceable cutters)

This drag is more robust when dealing with hard, frozen track than the Ginzus. Cutters are sturdy and locally purchased and easily replaced.

Recommend: KEEP

Suggest adding wheels or skis on side that fold up/down allowing for drag to be moved without cutters contacting the snow.



14) Diamond Harrow (36" wide X 49" long)

Recommend: SELL



15) Skidoo Alpine II (Yellow) Not Running

The Alpines have served the club very well over the years. Parts are no longer available for these machines and we are unable to find people willing to work on and maintain these them. They are obsolete. This status was part of the board's decision as part of the Country Grant application for the New Skandic. The board is no longer willing to accept the liability to continue running these machines.

Recommend: SELL



16) Skidoo Alpine II (Orange) Running condition

The Alpines have served the club very well over the years. Parts are no longer available for these machines and we are unable to find people willing to work on and maintain these them. They are obsolete. This status was part of the board's decision as part of the Country Grant application for the New Skandic. The board is no longer willing to accept the liability to continue running these machines.

Recommend: SELL